

### Physical & Mechanical Properties

Composition		Color Coordinates				Density (g/cc)		As cast Hardness (HV)	
		Karat	L*	a*	b*				
Cu	4.60%	10K 980	93.14	-1.28	13.1	10K 980	12.32	10K 980	95
Ag	83.40%								
Zn	12.00%								
Ni	0.00%								

### Melting & Casting Instructions

Temperatures			
	Karat	°C	°F
Pre alloying	10K	1030° C - 1040° C	1886° F - 1904° F
Casting	10K	920° C - 940° C	1688° F - 1724° F
Flask	10K	510° C - 650° C	950° F - 1202° F

Quench Time	20 - 30 Minutes	Remelting	50% Fresh Mix
-------------	-----------------	-----------	---------------

### General Instructions

- Very little boric acid flux is recommended. Do not use carbon flux such as soda ash, saltpeter etc. No flux needed in bottom pour automatic casting unit.
- Flouric based investment removers are the best for silicon oxide invisible coating. Use of aggressive acid causes corrosion and surface damage. United's brite cast investment removers works effectively.
- To calculate the weight of the metal needed (in grams), multiply density (gm/cc) with weight of wax (grams). Add 10% of the total weight for button.
- Gypsum bonded investment is recommended. Follow manufacturer's instruction for burnout cycle.

**Note:** There are proprietary metals in the formulation which are not included in the composition section.

**Technical Assistance:** Always available... Call [1-800-999-3463](tel:1-800-999-3463) / [1-800-999-FINE](tel:1-800-999-FINE)

E-mail - [techteam@unitedpmr.com](mailto:techteam@unitedpmr.com) Web-Site - [www.unitedpmr.com](http://www.unitedpmr.com)