

### Physical & Mechanical Properties

Composition		Melting Range		Density (g/cc)	Hardness (HV)
Pt	95.0%	1765° C - 1775° C	3209° F - 3227° F	20.80	95 (As Cast)
Co	5.0%				
Ir	0.0%				

### Melting & Casting Instructions

Temperatures			
	Casting Weight	°C	°F
Casting	Medium to Heavy	1965° C – 1975° C	3569° F – 3587° F
	Light weight detailed Castings	2000° C – 2010° C	3632° F – 3902° F
Flask	Heavy Weight mountings	649° C – 760° C	1200° F – 1400° F
	Medium Weight mountings	816° C – 871° C	1500° F – 1600° F
	Delicate Light mountings	927° C – 982° C	1700° F – 1800° F

<b>Quench Time</b>	15 - 20 Minutes
--------------------	-----------------

<b>Remelting</b>	50% Fresh Mix
------------------	---------------

<b>Investment Removal</b>	Recommended Pt Investment remover
---------------------------	-----------------------------------

### General Instructions

- Use only ceramic crucibles designed for melting platinum. Flux should never be used for Pt alloys.
- Use phosphate, acid bonded or other investment materials specifically designed for platinum casting. Use recommended Pt Investment remover to remove all investment before remelting.
- Wear proper eye protection when melting platinum alloys.